

Oil Field Environmental Incident Summary

Incident: 20150215174749 **Date/Time of Notice:** 02/15/2015 17:47

Responsible Party: BOH Trucking Inc.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: RIXEY 2-28H

Field Name: LONE TREE LAKE

Well File #: 23054

Date Incident: 2/15/2015 **Time Incident:** 11:00

Facility ID Number:

County: WILLIAMS

Twp: 157

Rng: 99

Sec: 28

Qtr:

Location Description:

Submitted By: Shane Knuchel

Received By:

Contact Person: Kelly Martinez
13745 55th St NW
Williston , ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels	4	Barrels	5	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 9/20/2016

Clean Up Concluded: 2/18/2015

Risk Evaluation:

None

Areal Extent:

All fluid contained within dike.

Potential Environmental Impacts:

Minimal

Action Taken or Planned:

Standing fluid was sucked up, and impacted soil recovered using a hydrovac.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved: Notified Tom Delling NDIC by phone on 2/15/2015 at 5:43 PM CT

Updates

Date: 2/16/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location within the diking according to the report. NDIC retains oversight.